




A.C.E.S



Part No: AMD 815



Replacement Dot Matrix VFD, Futaba 2x20 Display. Replacement part for Bally 02S-93190-VFD
Limited quantity - Refurbished unit - 30 Day warranty

Part No: AMD 816



Replacement Dot Matrix VFD, IEE 2x20 Display. Replacement part for Bally 02S-93290-VFD
Limited quantity - Refurbished unit - 30 Day warranty



Ameral Casino Electronic Supply

7 RAILROAD AVENUE, BROOKLAWN, NJ 08030

Ph. 856-456-9000

Fax 856-456-2522

www.ameral.com/aces.html

gaming@ameral.com

